Basket #	original #	current #	missing	location in pool 2
상자 번호	중간 대수	현재 대수	없는 대수	상자위치
171	40	38	2	0-2-3
194	40	39	1	0-32-1
173	40	36	4	0-32-3
174	40	36	4	0-17-1
180	39	37	2	0-30-3

1주간에 떨어진 연료봉 상태



CONFIRMED TO BE UNCLASSIFIED
DOE OFFICE OF CLASSIFICATION HS-93
T. Sieler DR DATE: 1/29/2009
T Sieler

DOES NOT CONTAIN
UNCLASSIFIED CONTROLLED
NUCLEAR INFORMATION

TRANSFERRED TO OTHER AGENCY
TRANSFER FOR DIRECT REPLY - DOE

SAT 2/3

YN92A

20080002437

D00013588


Filter rack
Shoe cover?
CenTec skid